WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

October 21, 2003

TO:	Internal File			
THRU:	Daron R. Haddock, Permit Supervisor			
FROM:	Dana Dean, P.E., Senior Reclamation Hydrologist			
RE:	2001 Fourth Quarter Water Monitoring, Sunnyside Cogeneration Association, Sunnyside Refuse/Slurry, C/007/035-57			
1. Was data submitted for all of the MRP required sites? Identify sites not monitored and reason why, if known:				
2. On what date does the MRP require a five-year resampling of baseline water data. See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.				
Resampling due date				
During the year preceding each re-permitting action: "Once every five years (prior to each application for permit renewal) one sample from each of the monitoring sites listed in Table 7-2A will be sampled and analyzed for the parameters listed in Table 7-2B." The Permittee should sample for baseline in 2002, 2007, etc.				
	equired parameters reported for each site? ents, including identity of monitoring site: YES NO			

Page 2	
C/007/0035-WQ01-4	1
October 21, 2003	

4. Were irregularities found in the data? Comments, including identity of monito	ring site:	YES 🖂	NO 🗌
Dissolved potassium at site F-2 (2 mg/l) 3.42 mg/l. Total dissolved solids at site ICE-1 the mean of 1388.77 mg/l. Specific conductivi deviations from the mean of 1244.20 mg/l.	(3956 mg/l) were	8.43 standard	deviations from
5. Were DMR forms submitted for all requi	red sites?		
	1 st month, 2 nd month, 3 rd month,	YES ⊠ YES ⊠ YES ⊠	NO
All DMRs reported "no flow".			
6. Were all required DMR parameters reported? Comments, including identity of monitoring site:		YES 🖂	NO 🗌
All DMRs reported "no flow".			
7. Were irregularities found in the DMR da Comments, including identity of monito	YES	NO 🗵	
All DMRs reported "no flow".			
8. Based on your review, what further action	ns, if any, do you	recommend?	
No further actions are necessary at this	time.		
O:\007035.SRS\WATER QUALITY\WQ01-4_57.DOC			